

VEHICLE SNAPSHOT

1967 Ford Mustang Coupe

Deep teal / black vinyl | 289 V8 / 4-speed manual | Classic vehicle record



REVIEW COMPLETE

VIN VERIFIED

16 / 16 REQUIRED

GOOD

Overall visible condition

3

Customer follow-up items

64,218

Displayed miles

A well-presented classic, with specific items to address

The exterior, cabin and engine compartment present consistently across the reviewed capture set. Three items merit attention: a small left-front paint chip, wear at the driver seat bolster and aged engine-compartment hose material. One light trim blemish is retained as a minor note; routine cosmetic wear is consolidated to keep the customer report focused.

VEHICLE / IDENTITY	CAPTURE / RELEASE
VIN / chassis: 7R01C000000	Captured: October 26, 2026
Door tag and body stamping: agreement recorded	Reviewed / released: October 27, 2026
Odometer: 64,218 displayed miles; total unknown	Required photos: 16 accepted / 16 required
Title / service records: 5 supporting entries	Engine video: 13.2 seconds, audio present

IDENTITY, SPECIFICATION & HISTORY

The vehicle behind the record

Identifier agreement, source attribution and a clear boundary between observation and authentication.

VIN VERIFIED

Door-tag image, body-stamp image and submitted identifier agree character for character.
Reviewer accepted the identity comparison.

FIELD	RECORDED DETAIL	REVIEW BASIS
VIN / chassis number	7R01C000000	E12 + S01 + D01 comparison
Year / make / model	1967 Ford Mustang hardtop coupe	Identifier format + vehicle appearance
Engine / transmission	289 cu in V8 / 4-speed manual	Owner record + visible configuration
Exterior / cabin	Deep teal / black vinyl	E01-E11 photographs
Displayed odometer	64,218 miles	E13 gauge image; reviewer transcribed
Total lifetime mileage	Unknown	Five-digit odometer; rollover not resolved
Owner-requested insured value	\$45,000	Owner request; not a market appraisal
Originality / matching numbers	Not authenticated	Casting dates and drivetrain serials not verified
Ownership / title	Owner-supplied title reviewed	Identifier agreement only; no registry search

Recorded work & supporting history


DATE	EVENT	SOURCE / STATUS
June 2020	Exterior refinish	D02 invoice; work description reviewed
April 2025	Brake hydraulic service	D03 invoice; scope and date reviewed
September 2026	Oil, filter and cooling-system service	D04 receipt; owner submission reviewed
October 26, 2026	Guided capture + supplemental close-ups	Marque Capture session; accepted

Identity scope: VIN verified means the supplied identifier evidence agrees in this record. It does not establish legal ownership, factory originality or matching-number components. Pre-1981 identifiers do not use the modern 17-character VIN checksum.

REVIEWED CONDITION & LOCATION MAP

Where attention is warranted

Customer findings are linked to specific views; routine minor wear remains in the full review record.



F01 Left-front fender

ATTENTION

Isolated finish chip at lower leading edge. Exposed substrate is visible; no spreading corrosion is established by these images. E01 + S02.

F02 Driver seat outer bolster

ATTENTION

Localized seam wear and vinyl creasing. Cushion support and seat structure require hands-on assessment. E09 + S03.

F03 Engine hose condition

FOLLOW-UP

Surface age cracking visible on an accessible hose section. Arrange a cold-engine technician inspection before extended use. E14-E16 + S04.

F04 Rear trim finish

MINOR NOTE

Light chrome pitting at the rear bumper corner. Cosmetic in the supplied views; retained as the single customer minor note. E05-E07.

Areas reviewed without a release-level concern

AREA	REVIEWED RESULT	SCOPE
Roof / glass / lamps	No material concern visible	Photo-based appearance review
Panel presentation	Generally consistent reflection lines	Subtle distortion may be hidden by gloss
Cabin / rear seating	Orderly presentation; no major tear visible	Accessible surfaces only
Engine bay	Broad coverage accepted	No road test, lift inspection or teardown

Release selection: 11 review entries resolved: 3 follow-up findings, 1 selected minor note and 7 cleared or consolidated entries. Every retained concern is linked to evidence. No issue is cleared solely because it is inconvenient to display.

EXTERIOR EVIDENCE & DETAIL REVIEW

The exterior, from every side

Eight guided walk-around views, plus a targeted detail image for the left-front finish concern.



E02 Front



E03 Front-right



E04 Right side



E05 Rear-right



E06 Rear



E07 Rear-left



E08 Left side



E01 Front-left / cover view



S02 Left-front finish detail

Reviewer disposition

Exterior views accepted for coverage, focus and framing. F01 is retained for local finish repair assessment; F04 records limited chrome pitting. Reflection patterns are consistent in the supplied overview views, but do not prove the absence of prior repairs, filler or concealed corrosion. Paint thickness was not measured.

Suggested care: Obtain a close-range inspection of the chipped edge, protect exposed material and agree a proportionate touch-up plan. Avoid interpreting a clean photograph as a structural or accident-history clearance.

CABIN, IDENTITY & ENGINE RECORDING

The details that complete the picture

Readable identifiers, three cabin angles and complementary engine views support the review.



E09 Driver door / front cabin



E10 Rear seating



E11 Passenger-door cabin



E13 Gauges / 64,218 miles



E12 VIN / identification plate



E14 Engine / front-top



E15 Engine / left side



E16 Engine / right side



Short start-and-idle clip retained.

Engine start & idle | human audiovisual review

REVIEWED OBSERVATION	INTERPRETATION / LIMIT
Engine starts and continues running	A 13.2-second sample; no load or road test
Audio present; start and idle audible	Does not rule out internal mechanical faults
F03 hose condition retained for inspection	Cold-engine technician assessment recommended

CAPTURE QUALITY & SURFACE ANALYSIS

Evidence with a traceable structure

Required coverage, supplementary files and confidence limits remain visible after customer release.

CAPTURE GROUP	REQUIRED / ACCEPTED	REFERENCES
Exterior walk-around	8 / 8	E01-E08
Cabin: driver / rear / passenger	3 / 3	E09-E11
VIN / identifier	1 / 1	E12; S01 body stamping
Gauges / displayed mileage	1 / 1	E13
Engine: front-top / left / right	3 / 3	E14-E16
Supporting close-ups	4 supplementary	S01-S04
Engine recording	1 supplementary; audio present	V01; 13.2 seconds
Owner-submitted documents	5 reviewed entries	D01-D05

Quality review & receipt controls

Capture receipt: October 26, 2026 at 10:42 AM PDT. All required views accepted after two glare retakes. VIN characters and odometer digits are readable in the accepted review state. The record retains original files, capture references, receipt time and version-linked reviewer decisions; customer presentation does not replace the source evidence.

3D surface supplement | extended analysis presentation

REGION	EXAMPLE OUTPUT	REVIEW INTERPRETATION
Left-front repair region	0.42 m2 usable coverage; 93% overlap	No reliable dent-depth estimate at chipped edge
Right quarter panel	0.31 m2 usable coverage; 91% overlap	Low-amplitude surface variation; no diagnosis
Gloss / trim / occlusion	Reflective zones masked from comparison	Retain photography; exclude weak depth values

Surface measurements require calibrated scale, repeatable alignment, confidence masks and a validated measurement pipeline. A point cloud alone cannot establish filler, paint thickness, hidden corrosion or structural integrity. RANGE 2 integration and these extended analytical outputs are represented here as future-state demonstration content.

OWNER-SUBMITTED DOCUMENTS

The work. The records. The story.

Owner uploads connect registration, restoration and maintenance to a continuing vehicle record.

OWNER SUBMITTED

Five supporting documents retained. Selected previews below show how uploaded records appear alongside the vehicle history.

DOCUMENT PREVIEW / EXTRACT

Evidence of registration

VEHICLE
1967 Ford Mustang

VIN / CHASSIS
7R01C000000

RECORD PERIOD
2026 registration

PERSONAL DETAILS
Address / plate withheld

D05 / Owner upload

DOCUMENT PREVIEW / EXTRACT

Exterior refinish

WORK DATE
June 18, 2020

RECORDED WORK
Prep, refinish and trim refit

INVOICE TOTAL
\$8,750.00

VEHICLE REFERENCE
1967 Mustang / owner file

D02 / Owner upload

DOCUMENT PREVIEW / EXTRACT

Brake service

WORK DATE
April 11, 2025

RECORDED WORK
Hydraulic service and bleed

INVOICE TOTAL
\$1,286.40

DISPLAYED MILEAGE
63,804 miles

D03 / Owner upload

Document register & review status

REF / UPLOAD	DOCUMENT / WORK RECORDED	REVIEW SCOPE
D01 / Oct 26, 2026	Title / ownership document	Identifier agrees; no title-registry search
D02 / Oct 26, 2026	Exterior refinish invoice / Jun 2020	Date, work description and amount read
D03 / Oct 26, 2026	Brake-service invoice / Apr 2025	Service scope and mileage transcribed
D04 / Oct 26, 2026	Oil / filter / cooling receipt / Sep 2026	Maintenance entry linked to history
D05 / Oct 26, 2026	Evidence of registration / 2026	Vehicle identifier matched to record

A record that grows with the car

Owners can add invoices, receipts, registration evidence, restoration photographs and service records as work is completed. Each upload is associated with its document date, submission date, vehicle and reviewer status. Original files remain in the controlled record; report previews omit personal details.

Reviewed does not mean independently authenticated: the document contents have been read and linked to this vehicle record. The issuer has not been contacted, payment has not been independently confirmed and an invoice does not prove current mechanical condition or legal ownership.

CUSTOMER ACTIONS & RELEASE RECORD

A clear path forward

A reviewed record preserves what was seen, what remains uncertain and what to do next.

PRIORITY	RECOMMENDED ACTION	REFERENCE
Before extended driving	Have a technician inspect the aged hose area with the engine cold; renew affected material as advised.	F03 / E14-E16 / S04
Preservation	Inspect and protect the left-front paint chip; agree a local finish repair if appropriate.	F01 / E01 / S02
Planned cosmetic care	Assess driver bolster seam wear with an upholstery specialist.	F02 / E09 / S03
Optional cosmetic care	Monitor rear trim pitting; address during routine detailing or trim restoration.	F04 / E05-E07

Reviewed & released

RELEASE CONTROL	RECORDED STATUS
Photo coverage and quality	Complete / 16 required views accepted
Identity comparison	VIN VERIFIED / identifier evidence agreement
AI-assisted observations	Reviewed, edited and classified before release
Customer finding selection	3 action items + 1 minor note; full review retained
Review authority	Condition Review Desk / reviewer role R-01
Release version / date	2.0 / October 27, 2026
Access and retention	Customer report scope; source files held in controlled record

Scope of this record

This is a visible-condition and evidence review, not a safety certificate, appraisal, title guarantee or mechanical warranty. No underside examination, diagnostic scan, compression test, road test, paint-depth survey or drivetrain-number authentication is established. Displayed mileage does not establish total lifetime mileage.

Example / demonstration report: All vehicle details, observations, measurements, documents and review entries are illustrative; photographs are AI-generated. VIN 7R01C000000 uses a period-style identifier with a zeroed sample sequence and is not assigned to an inspected vehicle. Extended scanner analysis illustrates intended future capability. No actual vehicle inspection or professional certification is represented.